Approved For Release 2002/06/25 : CIA-RDP89B00569R000400020126-0

[redacted] 25X1A

19 SEP 58 21 33

SECRET

HAT
RMB
WB

OPS
CC
Pi

DPS/DCI
3118
19 SEPTEMBER 1958

[redacted] 25X1A

DIRECTOR

SAPD/DCI (1,2,3,4,5,6,7,8)

S/C (9)

RLU

25X1A

2133Z 19 SEP 58

PRIORITY

ROUTINE

INDEXED IX PRIORITY

ROUTINE OPERATIONAL IMMEDIATE

OUT83696

TO: [redacted] INFO: [redacted] CITE: [redacted] 2626

25X1A

(IN 46777)

25X1A

1. IMMEDIATE REQUIREMENT EXISTS FOR ONE TIME INSPECTION OF SECURENESS OF P/N 277471 ELBOW AT FRONT ACCESSORY HOUSING OF -31 ENGINES. THIS ELBOW ATTACHES TO P/N 277470 OIL LINE WHICH ROUTES PRESSURE OIL TO TOP OF ENGINE ON LEFT SIDE. FURTHER SUGGEST INSPECTION OF SECURENESS OF P/N 204365 FITTING AND P/N 203424 O-RING AT ACCESSORY HOUSING.

2. INSPECTION WILL INCLUDE CONDITION OF THREADS AND PROPER SIZE OF FITTINGS. WHEN REPLACEMENT OF FITTING IS ACCOMPLISHED PROPER TROQUING AND SAFETYING WILL BE CLOSELY SCRUTINIZED TO ASCERTAIN PROPER FIT.

3. THREE CASES OF ~~IN~~ IMPROPER FITTING ON THIS PART NUMBER HAS CAUSED TWO OPERATIONAL FAILURES DUE TO LOSS OF OIL, WHICH INDICATES POOR QUALITY CONTROL DURING OVERHAUL, THEREFORE SUBJECT INSPECTION TO BE ACCOMPLISHED PRIOR TO NEXT VB. FLIGHT OF

25X1A

[redacted]

END OF MESSAGE

25X1A

[redacted]

COORD: AES WB

COORDINATING OFFICERS

SECRET

AUTHENTICATING OFFICER

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED Copy No.

Approved For Release 2002/06/25 : CIA-RDP89B00569R000400020126-0